

Production Tank External Inspection Checklist

Date: 02/20/12 Location: 11/05-67-049-22 Year & Serial Number: 2009 17381-25

Sticker/SAP Number: CC-15554 Manufacturer: Universal Size: 1000 BBL

Floor Thickness: 0.25 Shell Thickness: 0.25/1.875/1.875/1.875 Roof Thickness: 1.875

Liner: ☒ YES ☐ NO Comments: SES Gully Lake

Gas Line: CC-25545

Hard Pipe/Tubing: ☒ YES ☐ NO Comments: _____

Regulator: ☒ YES ☐ NO Comments: _____

Containment:

Type: ☐ Dyke ☒ Steel Comments: _____

Condition: ☒ Good ☐ Poor Comments: _____

Tank Base:

Supports Tank Properly: ☒ YES ☐ NO Comments: _____

Is Tank Leaning: ☐ YES ☒ NO Comments: _____

Floor Above Grade: ☒ YES ☐ NO Comments: _____

Dirt On Lip: ☐ YES ☒ NO Comments: _____

Adequate Drainage: ☒ YES ☐ NO Comments: _____

Tank Shell:

Painted: ☒ YES ☐ NO Comments: _____

Rusted Areas: ☐ YES ☒ NO Comments: _____

Visible Dents: ☐ YES ☒ NO Comments: _____

Signs of Leaks: ☐ YES ☒ NO Comments: _____

Insulation Blistered: ☐ YES ☒ NO Comments: _____

Insulation Stained: ☐ YES ☒ NO Comments: _____

Insulation Missing: ☐ YES ☒ NO Comments: _____

Tank Roof:

Insulation Blistered: ☐ YES ☒ NO Comments: _____

Rusted Areas: ☐ YES ☒ NO Comments: _____

Flat Sections: ☐ YES ☒ NO Comments: _____

Standing Water: ☐ YES ☒ NO Comments: _____

Corroded Through: ☐ YES ☒ NO Comments: _____

Ladder:

Full Cage: ☒ YES ☐ NO Comments: _____

Bolting Tight: ☒ YES ☐ NO Comments: _____

Shell Nozzles:

Plugs in Place: ☒ YES ☐ NO Comments: _____

Are flanges level: ☒ YES ☐ NO Comments: _____

Signs of Leaks: ☐ YES ☒ NO Comments: _____

Piping:

Flanges Aligned: ☒ YES ☐ NO Comments: _____

Shortbolting (flanges): ☐ YES ☒ NO Comments: _____

Supported: ☒ YES ☐ NO Comments: _____

Overall Condition: ☒ Good ☐ Fair ☐ Poor **Internal Inspection Req.** Yes ☒ No

Operator/Inspector: Rushford **Date:** 02/20/12