

MAGNETIC PARTICLE INSPECTION REPORT

CUSTOMER: *Husky Energy*

LOCATION: 13-4-44-23W3M

INVOICE: 39601

W.O.# 4068848

SN #: G03285 S1

CODE: API 653

INSPECTOR: Ken Pope

Signature: \_\_\_\_\_

Date: June 3,2011

Technician: ARDEN KERR

Assistant: Todd Clark

ARDEN KERR  
SNT LEVEL II  
CGSB 48.9712  
CGSB# 9914  
TECHNICIAN STAMP

Signature: *Arden Kerr*

Equipment Used: Contour Probe / Hand Held Yoke  
Ely Products Supramor 4 Black Particles  
White Contrast Paint 712  
Technique: MT 2  
Description: Continuous Wet / Black & White

Report: MT 37-148

WELD I.D.	SIZE	THICKNESS	STAMP	PASS	FAIL	DESCRIPTION
MP-1	N/A	N/A	JR	X		HOT BOX TACKS
MP-2	N/A	.250"	JR	X		PATCH
MP-3	N/A	.250"	JR	X		PATCH
MP-4	3/4"	3M	JR	X		THERMALWELL
MP-5	4"	STD	JR	X		NOZZLE
MP-6	N/A	.250"	JR	X		PATCH
MP-7	N/A	.250"	JR	X		REPAD
MP-8	N/A	.250"	JR	X		PATCH
MP-9	N/A	.250"	JR	X		PATCH
MP-10	N/A	.250"	JR	X		REPAD
MP-11	N/A	N/A	JR	X		LIFTING LUG
MP-12	4"	STD	JR	X		NOZZLE
MP-13	3/4"	3M	JR	X		THERMALWELL
MP-14	N/A	.250"	JR	X		PATCH

*Greg Braham*  
CGSB / SNT Level 3  
CGSB: 48.9712  
CGSB #: 8481

