

PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5 Date: 2014-06-04 SAP Equipment ID: 66128609

			VI	ESSE	LSTATI	C DAT	4				
Plant	ANSEL GAS I	PLANT C	Op Uni	t N/	Ά			Syste	m	N/A	
Prov. Insp. #	A0571608	С	CRN	U	0192.213	3		Equip	Tag #	20-	V-001
Equipment D	escription	INLET SEP	PARAT	OR				Seria	#	1230	6200
Manufacturer	•	TOROMON	IT PRO	CESS	SYSTEM	18		Vesse	el Class	S PRES	SURE VESSEL
Internal Acce	ss: X YES	NO Desc	criptio	n: 20'	OD MA	NWAY	•	Year	Built	2007	
MAWP 39	0	kPa / PSI		@	150		°C/°F	MDM.	Т	-20	°C/°F
CODE: UM	U U2	R	RT: 4	- 2	3 4			PWH	Γ: N/A	ı	
Diameter 48	3" OD Le	ngth (T/	T) N	/A n	nm/in C	AL 192	2 mm/in	Vertic	al	Hori	zontal
Shell Mat	'I N/A	T	Thickn	ess		N/A	mm / in	Corr A	llowand	ce N/A	nm / in
Head Mat	'I N/A	Т	Thickn	ess		N/A	mm / in	Corr A	llowand	ce N/A	nm / in
Nozzle Mat	'I N/A	Т	Thickn	ess		N/A	mm / in	Corr A	llowand	ce N/A	\ nm / in
Internal Coat	ing: YES NO) Ir	nterna	I Clad	I: Y E	S-	NO	Capa	city	N/A	m ³
Manway:	YES NO) Ir	nspec	tion P	ort: Y	ES	OH	Skirt	Legs	- Sad	dle
Nozzle Rating	g 600 I	b ANSI P	Painted	: t	YE	S	NO	Insula	ated	YE	S NO
				PRO	CESS D	DATA					
Product Desc	•						Swee		Sour		
Operating Pro	essure N/A			a / PSI			ting Tem	perature	N/A	١	°C / °F
					STATIC			1			<u> </u>
Carriel No.	Location	Set		Cap scfm/l	oacity	Manu	facturer	Model /	Туре	• • • • • • • • • • • • • • • • • • • •	ice Date /
Serial No.		Pressu	ıre	GPM							mpany
484642-18-A10	INLET PIPING	390 PSI			SCFM	FARE	RIS	26JA12	A-120	WIZAR	D VALVE
	- /-:		\	PS	V DETA		I D - C		<u> </u>	0: (
DDD Inlet	Type (Tr FLANGE	read/Flan	ige)		200	ANS	Rating		70.0	Size (ı	mm)
PRD Inlet	_				300 150				76.2		
PRD Outlet	FLANGE		NIC	E Ec.	uipment	rocoro	le		101.6		
Procedure#	Description	Manufact		L Equ	Model		13	Serial#		יח	ue Date
MT-1	WFMT	CONTOU		BES	B-300	i r)832		SSEPT-14
IVIII	VVI IVI I	2011100		,,,,,,	D 300				7002	00	<u> </u>

INSPECTION SUMMARY

EXTERNAL INSPECTION:

- 1) DATA PLATE IS SECURED IN PLACE AND IS LEGIBLE
- 2) SADDLE IN SECURED TO FOUNDATION AND DIRECTLY GROUNDED.
- 3) PSV IS LOCATED ON THE INLET PIPNG AND HAS AN ISOLATION VALVE THAT IS CARSEALED IN THE OPEN POSITION.
- 4) ATTACHED PIPING HAS SOME MINOR COATING DAMAGE, NO CORROSION IS PRESENT.
- PRESSURE GAUGE, TEMPERATURE GAUGE AND SIGHT GLASS ARE CLEAN, CLEAR AND VISIBLE.
- 6) ALL PIPING CONNECTIONS ARE PROPERLY FASTENED, NO EVIDENCE OF LEAKS.
- 7) NO DEFORMATION OR CORROSION FOUND ON THE SHELL OR HEADS.

INTERNAL INSPECTION:

- 1) 20" MANWAY UTILIZED FOR THE INTERNAL INSPECTION.
- 2) ALL ACCESSIBLE SHELL AND HEAD WELDS ARE TO IN GOOD CONDITION, WITH NO RELEVANT SIGNS OF DETERIORATION. WET FLUORESCENT MAGNETIC PARTICLE INSPECTION (MPI) COMPLETED ON 24" OF THE CIRC AND LONG SEAMS AT THE "T" INTERSECTIONS. REFER TO ATTACHED MPI REPORT #66128609 EQ INSPECTION REPORT 2014-06-04 MT A0571608 INLET SEPARATOR.
- 3) NO BLOCKAGES FOUND IN THE ACCESSIBLE NOZZLES.
- 4) NO EVIDENCE OF CORROSION OR EROSION FOUND ON THE SHELL AND HEADS.
- 5) INTERNAL COMPONENTS ARE IN GOOD VISUAL CONDITION.

SEPARATOR IS FIT FOR CONTINUED SERVICE.



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5 Date: 2014-06-04 SAP Equipment ID: 66128609

	RECOMMENDA	TIONS			
N/A					
	NCONFORMANCES / INSPE	CTION DEFI	CIENCIES		
N/A					
	INSPECTION PLA	ANNING			
Inspection Strategy	Availability		Inspection Interva	al	
Inspection Date	Date of Last Inspect		Date of Next Insp	ect	
			-		
	REPORT CERTIF	ICATION			
The signatures below certify that inspection the specified equipment is considered fit for	ns/tests have been completed in or service until the date of next i	n accordance inspection.	with the identified i	nspection s	strategy and that
			-A -		
Inspected by	CURTIS SINCLAIR	Centra	Dinela	Date	2014-06-04
Company	STREAMLINE INSPECTION	PESL#	00541	API#	35229
	STREAMLINE INSPECTION	FESL#	00341		33229
Reviewed and Approved by				Date	
		PESL#		API#	
Criticality Assessment Rerun		Inspection Pla	anning Rerun		
Assessed Next Inspection Date					



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5 Date: 2014-06-04 SAP Equipment ID: 66128609

DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	Location VISUA	NCR	Comments
V1	General Other (Please Explain)	GOOD			IN GOOD OVERALL CONDITION
V2	General Corrosion	GOOD			NONE PRESENT
V3	General Leaks	GOOD			NO EVIDENCE OF LEAKS NOTED
V4	Vibration	GOOD			NO VIBRATION ISSUES FOUND
V5	Dissimilar Flange Rating	GOOD			NO DISSIMILAR FLANGE RATING
V6	Ladder/Stairway	N/A			N/A
V7	Heads	GOOD			NO DEFORMATION OR CORROSION
V8	Guy Wires	N/A			N/A
V9	Electrical Ground	GOOD			DIRECT GROUNDING
V10	Painted Inactive Corrosion	GOOD			NONE
V11	Coating/Painting	GOOD			NO RELEVANT DAMAGE
V112	Expansion Joint or Bellows	N/A			N/A
V13	Gauge/Site Glass	GOOD			CLEAN, CLEAR AND VISIBLE
V14	Shell	GOOD			NO DEFORMATION OR CORROSION
V15	Jacket	N/A			N/A
V21	Support Other (Please explain)	GOOD			SECURED IN PLACE
V22	Foundation	GOOD			INTACT
V23	Anchor Bolts	GOOD			PROPERLY FASTENED
V24	Saddle/ Skirt	GOOD			NO DEFORMATION
V25	Davit	N/A			N/A
V26	Fireproofing	N/A			N/A
V31	Connections Other (Please explain)	GOOD			PIPING CONNECTIONS ARE PROPERLY FASTENED TOGETHER
V32	Small Branches	GOOD			NO EVIDENCE OF LEAKS FOUND
V33	Nozzles	GOOD			PROPERLY FASTENED
V34	Manways	GOOD			NO CORROSION OR WEAR PRESENT
V35	Reinforcing Pads	GOOD			WEEPING HOLES PRESENT
V36	Inadequate Thread Engagement	GOOD			ALL THREADS ADEQUATELY ENGAGED
V37	Bolting	GOOD			NO CORROSION OR WEAR
V38	Flanges	GOOD			NO CORROSION OR WEAR PRESENT
V39	Leak Clamps	N/A			N/A
V41	Insulation Other (Please explain)	N/A			N/A
V42	Damage	N/A			N/A
V43	Penetrations	N/A			N/A
V44	Insulation Jacket	N/A			N/A
V45	Banding	N/A			N/A
V46	Seals/Joints	N/A			N/A
V51	Relief Devices Other (Please explain)	GOOD			LAST SERVICED IN 2011 BY WIZARD VALVE
V52	Corrosion	GOOD			NONE
V53	Leaks	GOOD			NONE
V54	Restricted Inlet/Outlet	GOOD			ISOLATION VALVE CARSEALED IN THE OPEN POSTION
V55	Manual Operation Lever	N/A			N/A



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5 Date: 2014-06-04 SAP Equipment ID: 66128609

DETAILED INSPECTION VISUAL INTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)	GOOD			NO CORROSION PRESENT
V2	Corrosion (depth, length, width)	GOOD			NONE
V3	Erosion	GOOD			NONE
V4	Distortion	GOOD			NO DISTORTION FOUND
V5	Blisters	GOOD			NONE
V6	Deposits	GOOD			NONE
V7	Heads	GOOD			NO CORROSION OR DEFORMATION
V8	Welds	GOOD			WET FLUORESCENT MPI COMPLETED ON WELDS. REFER TO ATTACHED REPORT
V9	Nozzles	GOOD			NO BLOCKAGES FOUND
V10	Shell	GOOD			NO CORROSION OR DEFORMATION
V11	Gasket Surfaces	GOOD			NO WEAR OR CORROSION PRESENT
V21	Internals Other (Please explain)	GOOD			
V22	Demister	N/A			N/A
V23	Baffle /Wier	GOOD			NO DAMAGE
V24	Sparger	N/A			N/A
V25	Thermowells	N/A			N/A
V26	Metallic Linings	N/A			N/A
V27	Nonmetallic Linings	N/A			N/A
V28	Trays	N/A			N/A
V29	Tray Rings	N/A			N/A
V30	Other Welded Attachments	GOOD			NO DAMAGE

DETAILED INSPECTION OTHER TECHNIQUES

ID	Location	Observation/Measurement	Acceptance Criteria	NCR	Comments
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					

DETAILED INSPECTION UT THICKNESS

CML	Nom. Thk	Current Reading	Short Term Corr Rate	Long Term Corr Rate	Remaining Life	Comments



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5

Date: 2014-06-04

SAP Equipment ID: 66128609

PHOTOS








DATA PLATE



VESSEL OVERVIEW









ATTACHED PROCESS PIPING AND VALVES



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5

Date: 2014-06-04

SAP Equipment ID: 66128609





SEPARATOR PSV

PSV DATA PLATE





PSV SERVICE TAGE (1)

PSV SERVICE TAG (2)





20" MANWAY FLANGE SEALING SURFACE




PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5

Date: 2014-06-04

SAP Equipment ID: 66128609





PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD:07-27-051-19W5

Date: 2014-06-04

SAP Equipment ID: 66128609



Husky Energy

Location Name: ANSELL GAS PLANT LSD: 7-27-51-19W5

A#: A0571608 Equipment/Tag No. V101

Equipment Description: INLET SEPARATOR Serial Number: 12306200

CRN: (or other ID#) U0192.213

MAWP: 390 PSI Design Temp: 150°F Shell Material: SA-516-70N Head Material: SA-510

Shell Material:SA-516-70NHead Material:SA-516-70NShell Thickness:0.625"Head Thickness:0.5625"

Corrosion Allowance: 0.0625" Date Built: 2007

Size: 44" Manufacturer: TOROMONT PROCESS

SYSTEMS


RT: Pipe / Rolled Plate: ROLLED PLATE

Notes:





Husky Energy





Husky Energy









Ultrasonic Corrosion Survey

Survey Name: Husky Energy Date: Jun 3, 2014

Inspector: W. Gill

LSD:	07-27-051-19W5M	Area:	Ansell			Location:	Gas Plant		
A #:	A0571608	Tag Number:				Vessel Name:	Inlet Sepa		
CRN:	U0192.213	Year Built:	2007			Serial Number:	12306200		
		Vessel CA:	1.5875	mm		Manufacturer:	Toromont	Process Sy	stems
		Shell MAWP:	390psi	MAWTF:	150°F	Tube MAWP:		MAWTF:	
TML De	escription		Baseline					Material:	SA-516-70N
05	Head		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Ellipsoidal	Min	16.180		12.700	1.588	14.288		
OD:	44"	Avg	16.280						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	SA-516-70N
10	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Cylindrical	Min	16.150		14.288	1.588	15.875		
OD:	44"	Avg	16.330						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	SA-516-70N
15	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Cylindrical	Min	16.310		14.288	1.588	15.875		
OD:	44"	Avg	16.590						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	SA-516-70N
20	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Cylindrical	Min	16.640		14.288	1.588	15.875		
OD:	44"	Avg	16.870						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:



Ultrasonic Corrosion Survey

Survey Name: Husky Energy Date: Jun 3, 2014

Inspector: W. Gill

LSD: A #: CRN:	07-27-051-19W5M A0571608 U0192.213	Area: Tag Number: Year Built: Vessel CA: Shell MAWP:	Ansell V101 2007 1.5875 390psi	mm MAWTF:	150°F	Location: Vessel Name: Serial Number: Manufacturer: Tube MAWP:	Gas Plant Inlet Sepa 12306200 Toromont		stems
TML De	escription		Baseline					Material:	SA-516-70N
25	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Cylindrical	Min	16.150		14.288	1.588	15.875		
OD:	44"	Avg	16.460						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	SA-516-70N
30	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Cylindrical	Min	16.100		14.288	1.588	15.875		
OD:	44"	Avg	16.330						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	SA-516-70N
35	Head		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Ellipsoidal	Min	15.950		12.701	1.588	14.288		
OD:	44"	Avg	16.180						Remaining Life:
Spec:	ASME VIII Div.1	Comments:							Retirement Date:
TML De	escription		Baseline					Material:	A-234-WPB
40	Shell		2014		Flag	CA	Nominal	T Min	Corr. Rate
Shape:	Gas Boot	Min	12.400		11.113	1.588	12.700		
OD:	12.75"	Avg	12.950				Assumed		Remaining Life:
Spec:	ASME B31.3	Comments:							Retirement Date:



Spec: ASME VIII Div.1

Comments:

Ultrasonic Corrosion Survey

Survey Name: Husky Energy Date: Jun 3, 2014

Inspector: W. Gill

Retirement Date:

Gas Plant LSD: 07-27-051-19W5M Ansell Location: Area: Tag Number: V101 **Inlet Separator** A #: A0571608 Vessel Name: 2007 Serial Number: 12306200 CRN: U0192.213 Year Built:

Vessel CA: 1.5875 mm **Manufacturer:** Toromont Process Systems

Shell MAWP: 390psi MAWTF: 150°F Tube MAWP: MAWTF:

TML De	escription		Baseline				Material:	A-234-WPB	
45	Head		2014	Flag	CA	Nominal	T Min	Corr. Rate	
Shape:	Gas Boot	Min	10.900	11.113	1.588	12.700	4.572	0.257	
OD:	12.75"	Avg	11.480			Assumed		Remaining Life:	26.02 Years
Spec:	ASME B31.3	Comments:	No Corrosion Found					Retirement Date:	6/10/2040
TML De	escription		Baseline				Material:	A-234-WPB	
50	Nozzle		2014	Flag	CA	Nominal	T Min	Corr. Rate	
Shape:	Cylindrical	Min	16.100	11.113	1.588	12.700			
OD:	22"	Avg	16.330					Remaining Life:	
Spec:	ASME VIII Div.1	Comments:						Retirement Date:	
TML De	escription		Baseline				Material:	SA-516-70N	
55	Shell		2014	Flag	CA	Nominal	T Min	Corr. Rate	
Shape:	Cylindrical	Min	15.950	11.113	1.588	12.700			
OD:	22"	Avg	16.180			Assumed		Remaining Life:	
Spec:	ASME VIII Div.1	Comments:						Retirement Date:	
TML De	escription		Baseline				Material:	SA-516-70N	
60	Head		2014	Flag	CA	Nominal	T Min	Corr. Rate	
Shape:	Ellipsoidal	Min	12.400	11.113	1.588	12.700			
OD:	22"	Avg	12.950			Assumed		Remaining Life:	



Spec: ASME B31.3

Comments:

Ultrasonic Corrosion Survey

Survey Name: Husky Energy Date: Jun 3, 2014

Inspector: W. Gill

Retirement Date:

LSD:	07-27-051-19W5M	Area:	Ansell			Location:	Gas Plant
A #:	A0571608	Tag Number:	V101			Vessel Name:	Inlet Separator
CRN:	U0192.213	Year Built:	2007			Serial Number:	12306200
		Vessel CA:	1.5875	mm		Manufacturer:	Toromont Process Systems
		Shell MAWP:	390psi	MAWTF:	150°F	Tube MAWP:	MAWTF:

TML De	escription		Baseline			Materia	I: A-234-WPB
65	Nozzle		2014	Flag	CA	Nominal T Min	Corr. Rate
Shape:	90° Elbow	Min	10.720	9.601	1.372	10.973	
OD:	6.625"	Avg	11.400			Assumed	Remaining Life:
Spec:	ASME B31.3	Comments:					Retirement Date:
TML De	escription		Baseline			Materia	l: A-234-WPB
70	Piping		2014	Flag	CA	Nominal T Min	Corr. Rate
Shape:	90° Elbow	Min	3.710	3.423	0.489	3.912	
OD:	2.375"	Avg	4.110			Assumed	Remaining Life:
Spec:	ASME B31.3	Comments:					Retirement Date:
TML De	escription		Baseline			Materia	I: SA-516-70N
75	Piping		2014	Flag	CA	Nominal T Min	Corr. Rate
Shape:	90° Elbow	Min	3.990	3.423	0.489	3.912	
OD:	2.375"	Avg	4.290			Assumed	Remaining Life:
Spec:	ASME B31.3	Comments:					Retirement Date:
TML De	escription		Baseline			Materia	l: A-234-WPB
80	Piping		2014	Flag	CA	Nominal T Min	Corr. Rate
Shape:	90° Elbow	Min	8.280	7.623	1.089	8.712	
OD:	2.375"	Avg	8.740			Assumed	Remaining Life:



Ultrasonic Corrosion Survey

Survey Name: Husky Energy Date: Jun 3, 2014

Inspector: W. Gill

Gas Plant LSD: 07-27-051-19W5M Ansell Location: Area: A0571608 Tag Number: V101 **Inlet Separator** A #: Vessel Name: U0192.213 2007 Serial Number: 12306200 CRN: Year Built:

Vessel CA: 1.5875 mm **Manufacturer:** Toromont Process Systems

Shell MAWP: 390psi MAWTF: 150°F Tube MAWP: MAWTF:

TML De	scription		Baseline				Material:	A-234-WPB
85	Piping		2014	Flag	CA	Nominal	T Min	Corr. Rate
Shape:	90° Elbow	Min	3.580	3.423	0.489	3.912		
OD:	2.375"	Avg	3.990			Assumed		Remaining Life:
Spec:	ASME B31.3	Comment	:s:					Retirement Date:
TML De	scription		Baseline				Material:	A-234-WPB
90	Piping		2014	Flag	CA	Nominal	T Min	Corr. Rate
Shape:	90° Elbow	Min	8.150	7.156	1.022	8.179		
OD:	8.625"	Avg	8.530					Remaining Life:
	ASME B31.3							Retirement Date:

FORM U-1A MANUFACTURER'S DATA REPORT FOR PRESSURE VESSELS (Alternative Form for Single Chamber, Completely Shop or Field Fabricated Vessels Only) As Required by the Provisions of the ASME Code Rules, Section VIII, Division 1

1.	Manufactured and	J certified by	Toromont Pr	rocess Systems	;, 10121 Barl	iow Trail NE, (Calgary, Alber	ta, Canada, T3.	J 3C6 (A)5	71408			
	Manufactured for			Toromont Process Systems , 10121 Barlow Trail NE, Calgary, Alberta, Canada, T3J 3C6 (A)57/508 (Name and address of manufacturer) Husky Energy Inc. 707 - 8th Avenue S.W.Calgary, AlbertaT2P 3G7 (Name and address of purchaser)									
3.	Location of installa	ation		Site: Ansell Gas Plant									
4.	4. Type <u>Horizontal</u> 123				0192.213	and address)	12306-401 Rev0			2007			
5.	(Horiz. or The chemical and	or vert., tank) I physical prop	Mfgr's serial) operties of all pa		(CRN) requirements	of material :	(Drawing No.) specifications			(Year built) PRESSURE VESSEL			
	CODE. The design								~~~	04			
	to	2006	*F************************************							_			
6.	Shell:	Addenda (D SA516-70N		.625"	Code Case Nos. " 0.0625" 3' 10.75				Special Service	e per UG-120(d) 16' -0"			
- -	Mati	tl. (Spec. No., Gra	rade)	Nom. Thk. (in.)	.) C	Corr. Allow. (in.)		oiam. I.D. (ft. & in.)		ngth (overall) (ft. & in.)			
7.		Type 1 I, Dbl.,Sngl.,Lap, Bu	Full Butt) R.T. (Spot or		H.T. Temp.(.(°F) Time (h	hr) G	Type 1 Girth,(Welded,	Spot R.T. (Spot	.70 2 Eff.(%) No. of			
Q.	Heads: (a) Matl.			16-70N		(b) Mati	Dbl.	l.,Sngl.,Lap,Butt)	or Full) SA516-70N	Courses			
ο.	Heads. (a) mac			No., Grade)			•		(Spec. No., Grade)				
	Location (Top,	Minimum	Corrosion	Crown	Knuckle	Elliptical	Conical	Hemispherica		Side to Pressure			
(a)	Bottom, Ends) End	7hickness 0.5625"	0.0625"	Radius -	Radius -	Ratio SE 2:1	Apex Angle	Radius -	Diameter -	(Convex or Concave) Concave			
(b)		0.5625"	0.0625"	-	- 1	SE 2:1	-			Concave			
<u> </u>	If removable, bolts			eninas)									
_	,	-			-ci at	****n		ec. No Gr Size. N	lo.)	- °F.			
9.	MAWP	(internal)		(external)				internal)	• -	external)			
	Min. design metal			at <u>390</u>	Psi. F	Hydro., pneu			50	07 psi.			
10.	Nozzles, inspectio	on and safety	·· valve opening	16.									
<u>. </u>	Purpose	T	Diam.		T		Nom. Rei	einforcement	How Attached				
	Purpose nlet, Outlet, Drain)	No.	or Size	Туре	Mati	d.	Thk.	Matl.	10W 7555	Location			
		<u> </u>			• • • • • • • • • • • • • • • • • • • •		•••	-0DM					
<u></u>		+		SEE	ATTAC	HED +	U4	FORM					
\vdash		-											
Ц Ч1.	Supports: Skirt	No No	Lugs No		No Oth	her S	aqqle	Attached	Shell	& Welded			
	••	(Yes or no)	(No.))	(No.)	(De	escribe)		(Wher	ere and how)			
2. Remarks: Manufacturer's Partial Data Reports properly identified and signed by Commissioned Inspectors have been furnished for the following													
	items of the report		pa					identifying stamp)	4	101 D-v 1D			
	Item: V101		228 Cubic Fe	et Ves	ssel Type:	Inlet Separ	rator	Construction	า Drawing: า	2306-401 Rev.1B			
-	Impact Testing: E	xempt, per	UG-20(1)										
				CERTIFICA	TE OF SHO	P/FIELD COM	MPLIANCE						
w	e certify that the s	statements m	ade in this repo	ort are correct a	and that all d	details of des	sign, material	I, construction	, and workmar	nship of this vessel			
co	onform to the ASI	ME Code for	or Pressure Ve	ssels, Section	ı VIII, Divisi	ion 1. "U" (Certificate o	of Authorizatio	on No. <u>33</u>	3,658			
1		ber 26, 2008		Torr		- Contome		Cianad	\rightarrow	,			
Da _	ate 22Mari	<u>)+</u>	o. name	TOIOI	omont Process (Manufac			_ Signed	(Rer	presentative)			
	CERTIFICATE OF SHOP/FIELD INSPECTION												
1 .	essel constructed b			Foromont Process			at		<u>v. Alberta, Ca</u>				
] I, '	the undersigned, he Alberta	olding a valid	commission is:		lational Board employed by			essel Inspecto	rs and/or the a	State or Province of			
-		component de	escribed in this				Man	1602	107	and state that,			
to	to the best of my knowledge and belief, the Manufacturer has constructed this pressure vessel in accordance with ASME Code, Section VIII,												
Di	Division 1. By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the pressure vessel described in this Manufacturer's Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for												
pr	ressure vessel desci yy personal injury oi	ribed in this vr-property da	Manutacturer s amage or a loss	 Data Report of any kind ar 	:. Furtnermo	ore, neitner u ir connected	me Inspector with this inst	nor his employ pection.	/er snan ne nan	JIE IN ANY MAINING TO-			
	te $\frac{7}{3}$	Sig		Som	10st		nmissions	altas		- 1 N- 3			
		•		(Authorized le	enector)			[Nat'l Board (i'	incl. endorsements)	, State, Prov. and No.)			

FORM U-4 MANUFACTURER'S DATA REPORT SUPPLEMENTARY SHEET As Required by the Provisions of the ASME Code Rules, Section VIII, Division 1

i. Mandidiaota	red and certified by	Toro	mont Proce	ess Systems , 10121	Barlow Trail NE, Calgary, Alberta, Calgary, Alberta, Calgary	nada, T3J	3C6			
2. Manufactu	(Name and address of manufacturer) Husky Energy Inc. 707 - 8th Avenue S.W.Calgary, AlbertaT2P 3G7 (Name and address of purchaser) Site: Ansell Gas Plant									
Location o										
4. Type:	re)			et Separator	<u> </u>			306200 s. serial No.)		
	U0192.213		_	12306-4	101 Rev0	_ Nat'l. Bd. No.)		2007		
	(CRN)			(Draw	Drawing No.) (N			(Year built)		
Remarks										
Data Report	Purpose (Inlet,	No.	Diam. or Size	Туре	Matl.	Nom. Thk	Reinforcement	How Attached	Location	
10 M1	Manway	1	20"	CL 300 RFWN	SA-105N / SA-106B	.500"	_	UW-16.1c	Shell	
10 B1	Boot	1	12"	SWB	SA-234WPB/ SA-106B/SA51-70N	.500"	-	UW-16.1c	Shell	
10 N1	. Inlet	1	6"	CL 300 RFWN	SA-105N / SA-106B/SA234-WPB	.864"	-	UW-16.1c	Shell	
10 N2	Gas Outlet	1	6"	CL 300 RFWN	SA-105N/SA234-WPB/SA106B	.432"	-	UW-16.1c	M1	
10 N3	LC	1	4"	CL 300 RFWN	SA-105N / SA-106B	.674"	-	UW-16.1c	Shell	
10 N4	Liquid Outlet	1	2"	CL 300 RFWN	SA-105N / SA-106B	.343"	-	UW-16.1c	Shell	
10 N5	Drain	1	2"	CL 300 RFWN	SA-105N / SA-106B	.343"	-	UW-16.1c	B1	
10 C2	PI	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C3	TI	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C4A	LSL	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C4B	LSL	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	B1	
10 C5A	LSL	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C5B	LSL	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
√0 C6A	LSHH	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
C6B	LSHH	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C7A	LG	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C7B	LG	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	B1	
10 C8A	LG	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C8B	LG	1	3/4"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C9A	LC	1	1 1/2"	NPT CPLG	SA-105N	6000#	-	UW-16.1c	Shell	
10 C9B	LC			SA-105N	6000#	-	UW-16.1c	Shell		
1000							Shell			
									-	
		<u> </u>								
		 	<u> </u>							
Certificate of Au	uthorization: Type		"U"	. No.	33,658 Expires No	vember 2	26, 2008			
Date <u>2211</u>	bro7 Nam	ne		Toromont Pro		Signed _	Repre	sentative)		
<u>7</u>	13/22		Name			issions $\underline{\mathcal{L}}$	(Nat') Board (incl. end		roy, and No.)	

REPORT: 66128609 - EQ - INSPECTION REPORT - 2014-06-04 - VE VI - A0571608 INLET SEPARATOR

Bay 5, 240040 Frontier Place SE Rocky View, Alberta T1X 0N2



DATE:

04-Jun-14

PAGE: 1 OF 2

MAGNETIC PARTICLE EXAMINATION REPORT

			1•1	IAGNETIC	IANTIC		IATINA I I	JIV IXEL	OKI		
CLIENT:		HUSKY ENER	GY			CONTRA	CTOR:	N/A			
LOCATION	NAME:	ANSEL GAS F	PLANT			STREAM	LINE JOB#	14-226			
LOCATION	l:	07-27-051-19V	V5			CLIENT F	PO#:	N/A			
ITEMS EXA	AMINED:	INTERNAL WI	ELDS OF INLE	T SEPARATO	R, A057160	08, SAP #6	6128609, E	Q# 20-V-00	01		
PROCEDU	RE:	MT-3A	ACCEP	TANCE CRITI	ERIA:	ASME VIII	DIV. 1 APP. 6	3	SPECIFICATION:	ASME V ART. 7	
					EQ	UIPMI	ENT				
√ YOKE	✓ AC	□ DC ☑ C	ONTINUOUS	RESIDUAL 🗸	120Volt	12Volt	Serial #:	20832	Last Cal. Da	te: 03-Sep-13 Prod Spacing 3"	- 8"
☐ 100 W TR	OUBLE LIGH	Γ*	W YOKE LIGHT*	☐ HALOGEN	N LIGHT [OTHER:			*Light Source Inte	ensity Demonstrated: ≥100fc	
✓ BLACKLIG	HT	Serial #:: 1Z1	11	Last	t Performar	nce Check	: 04-May-14		Minimum Black Li	ight Intensity: ≥1000µW/cm²	
☐ LIGHT ME	TER	Serial #:: 448	34/7968		Last Calibra	ation Date	:		Excess Particles F	Removed via Flow or Exhalat	ion
TEST MED	IUM MAN	UFACTURER:	M	agnaflux	M	IEDIUM T	YPE / SIZE:	Supramor 4	4 Black (<0.5 μ) / WCF	712	
DRY	COLOR:]	✓ FLUORESCENT	☐ BLACK ON	N CONTRAST V	WHITE	APPLICAT	TON METH	HOD :	RAY DOWDER PUFFER	
SURFACE	CONDITIO)N: □ CLEAN BASI	E METAL 🗌 AS GI	ROUND 🗹 WIRE	E WHEEL BUFF	FED AS	WELDED 🗌 PA	AINTED 🗌 S	AND BLAST	Material: C/S	
				EXAMIN A	ATION I	DETAI	LS AND	RESUL	TS		
SCOPE:	WET FLU	ORESCENT MA	AGNETIC PAR	TICLE INSPEC	CTION WAS	S COMPLE	ETED ON TH	HE FOLLO	WING WELDS LOC	ATED INSIDE OF THE INLET	
;	SEPARAT	OR, A0571608	, SAP #661286	09, EQ# 20-V-	001:						
	-24" IN ALL	DIRECTIONS	ON THE T INTE	RSECTIONS C	OF THE CIR	CULAR W	ELD SEAM A	AND LONG	ITUDINAL WELD SE	AM OF BOTH HEAD TO CAN	
,	WELDS, A	ND THE MIDDL	E SECTION CA	N TO CAN WE	LD						
RESULTS	NO RELE\	/ANT INDICAT	IONS WERE F	OUND ON TH	E WELDS I	INSPECTE	ED AS LISTE	ED ABOVE	. ALL WELDS ARE	ACCEPTABLE TO CODE.	
]	REFER TO	THE IMAGES	ON PAGE 2 C	F THIS REPO)RT						
TECHNICIA	AN/CERTII	FICATION: CUR	TIS SINCLAIR - CGSB/ 53 #29348, IPV #541	SNT-TC-1A UT I / MT	II / PT II #12425,	API 510 #3522	9,		CLIENT: GREG	GUENETTE	
SIGNATUR			1	4			HARGES RI	F.	APPROVAL:		
SIGNATUR	C.	Ci	enter (inela			JOB#14-226	6			
ASSISTAN	T:	N/A									

REPORT: 66128609 - EQ - INSPECTION REPORT - 2014-06-04 - VE VI - A0571608 INLET SEPARATOR

Bay 5, 240040 Frontier Place SE Rocky View, Alberta T1X 0N2



DATE:

04-Jun-14

PAGE:


2 OF 2

MAGNETIC PARTICLE EXAMINATION REPORT

CLIENT:	HUSKY ENERGY	CONTRACTOR:	N/A				
LOCATION NAME:	ANSEL GAS PLANT	STREAMLINE JOB#	14-226				
LOCATION:	07-27-051-19W5	CLIENT PO#:	N/A				

ITEMS EXAMINED: INTERNAL WELDS OF INLET SEPARATOR, A0571608, SAP #66128609, EQ# 20-V-001

EXAMINATION DETAILS AND RESULTS







INLET SEPARATOR DATA PLATE

EAST HEAD CIRC WELD T INTERSECTION

CAN TO CAN CIRC WELD T INTERSECTIONS



WEST HEAD CIRC WELD T INTERSECTION