



Wizard
VALVE SERVICES LTD.

PSV Final Inspection Test Report

5811 - 2nd Ave Edson, AB. P.O. Box 7903 Edson, AB, T7E 1V9
Phone: (780) 712-4055 Fax: (780) 723-5979

INITIAL INSPECTION	REFERENCE DATA	Date: <u>11-May-16</u> W.O.: <u>22628</u> ID: <u>12</u>	
		Customer: <u>Husky Oil</u>	Location: <u>12-05-54-21 W5M</u> Field: <u>GALLOWAY</u>
CONDITION RECEIVED	Make: <u>FARRIS</u> Model: <u>26HA10-120</u> S/N: <u>437853-1-A11</u> Other S/N: _____		
	Inlet: <u>RF Flanged</u> Size <u>1.50 in.</u> Outlet: <u>RF Flanged</u> Size <u>3.00 in.</u> Orifice: <u>H</u> Tag: <u>PSV-300</u>		
	Set Pressure <u>230 PSI</u> <u>1586 KPA</u> Back Pressure: <u>----- PSI</u> <u>----- KPA</u> Cold/Diff Set Press: <u>230 PSI</u> <u>1585.85 KPA</u>		
	Cap Assembly: <u>Closed</u> Lift Lever: <u>No</u> Capacity: <u>3.675 SCFM</u> Temp: <u>-----</u> Tag G: <u>SAP 66068140</u>		
CRITICAL INSPECTION	Code Symbol: <u>UV</u> CRN: <u>0G2369.5C</u> Vessel ID: <u>STABILIZER TOWER</u> Vessel No: _____		
	Customer Instructions: <u>Pretest & Repair</u> Reset Required ☐		
	New Pressure: <u>PSI</u> KPA New Capacity: _____		
	Pretest: Simmer: <u>235 PSI</u> <u>1,620 KPA</u> Set Pressure: <u>235 PSI</u> <u>1620 KPA</u> Reseat: <u>218 PSI</u> <u>1503.11 KPA</u>		
FINAL TEST	Test Gauge ID: <u>Dig 1</u> <u>1-600</u> Tested By: <u>LC</u> Leakage: <u>15 BPM</u>		
	Comments: _____		
	Visual Condition <u>Minor</u> Other: _____ Data Plate: <u>OK</u>		
	Seal Condition: Top: <u>Intact</u> Bottom: <u>NA</u> Insignia: <u>WIZ</u> Date of Last Service: <u>05/11</u>		
FINAL INSPECTION	Indicate Fouling <u>Rust</u> Blow Down Ring Setting (Upper) <u>-----</u>		
	INLET ☒ OUTLET ☒ BODY ☒ BONNET ☐ No. of Notches: (Lower) <u>-4</u>		
	DISMANTLE: <u>HV</u> INSPECTION: <u>HV</u> REASSEMBLY: <u>ib</u>		
	MEDIUM: <u>Air</u> SET PRESSURE DEFINITION <u>Pop</u>		
FINAL INSPECTION	FINAL TEST Simmer <u>230 PSI</u> <u>1586 KPA</u> Set Press <u>230 PSI</u> <u>1586 KPA</u> Reseat <u>221 PSI</u> <u>1524 KPA</u> Leakage <u>2 BPM</u>		
	BACK PRESSURE TEST <u>60 PSI</u> <u>414 KPA</u> ADJ. RING SETTING (NOTCHES) UPPER <u>-----</u> LOWER <u>-5</u>		
	Test Gauge ID: <u>Dig 1</u> <u>1-600</u> Tested By: <u>RB</u> Date Tested: <u>13-May-16</u>		
	SEAL INSTALLED: TOP ☒ BOTTOM ☒ FLANGE/ THREAD PROTECTORS INSTALLED ☒ PRIMED / PAINTED ☒		
FINAL INSPECTION	COMMENTS: <u>EXTRA CLEANING NEEDED</u>		
	FINAL INSPECTION: <u>TM</u> CUSTOMER/INSPECTION _____		