



**Technical
Safety Authority
of Saskatchewan**

Boilers and Pressure
Vessel Safety Unit

#330 - 1855 Victoria Avenue
Regina, Saskatchewan
S4P 3T2

Inspection Certificate

66102898

Issued under the provisions of The Boilers and
Pressure Vessel Act

Husky Energy
c/o Ray Trachuk
4429 - 44th Street, Highway 16 East
Lloydminster, Saskatchewan
Canada
S9V 0Z8

Description:

Other - Pressure Vessel
CRN P6749.23 Mft. Natco Canada Ltd. - Dessicant
Vessel

Location:

Northminster
LSD 10-19-50-27W3M

Certificate No: 205881
Date Inspected: 2011-11-02
Inspector: Holuk, Larry
Licence No: 0019670
Serial No: 42586-55
Shell Pressure: 1965 kPa **Length:** 1.83 m **Diam:** 0.51 m


Chief Inspector

In the event of an explosion, rupture or serious overheating of a boiler or pressure vessel,
notice shall be sent forthwith to the Chief Inspector.

66102898

Technical
Safety Authority
of Saskatchewan

Boiler and Pressure Vessel
Safety Unit
#330 - 1855 Victoria Avenue
REGINA SK S4P 3T2

Report Number: 205881
Previous Inspector:
Licence Number: 19670 - (Acceptance Pending)
Serial - Unit Number: 42586-55 - 00212
Plant: 0 (pieces)

Equipment:	Owned By:
Bid/Oilfield: Northminster	Husky Energy (306) 825 - 1234 (Phone)
Address: 10-19-50-27W3M	c/o Ray Trachuk (780) 205 - 2092 (Cell)
City/Town:	4429 - 44th Street, Highway 16 East (306) 825 - 1159 (Fax)
	Lloydminster, Saskatchewan S9V
LLD: 10-19-50-27W3M	028
Community:	Canada
District: 5	

Item Type:	39 - Other - Pressure Vessel (Provincial)		
Inspector Description:			
Owner Description:	CRN P6749.23 Mfr. Natco Canada Ltd.	Dissident Vessel	
CRN:	P 6749.23	Mobility:	Stationary
NB:		Shell WP:	1965
Manufacturer:	NATCO	Tube WP:	
Manufactured Date:	2001-01-01	Diameter (m):	0.51
Last Internal Insp.:		Length (m):	1.83
Inspection Method:	Acceptance		
Next Inspection Date:	2016-11-02 (yyyy-mm-dd)	Install Permit No.:	13180
Assigned to Inspector:	0445 - Larry Holuk		
Previous Conditions:			

Inspection Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/Not Operating

1. Safety Valve:	A	7. Inspection Openings:	A	13. Nameplate:	A
2. Level Gauge:	A	8. Associated Piping:	A	14. Other:	
3. Pressure / Temp Gauge:	A	9. Shell:	A		
4. Tubesheet:	N	10. Heads:	A		
5. Tubes:	N	11. Data Report:	A		
6. Insulation:	N	12. Sask Design Registration:	A		

Comments/Repairs or Corrective Action Required:

Unable to do inspection on: (yyyy-mm-dd)

Reason inspection was not done:

Items Classified with an "R" must be repaired or corrected by : (yyyy-mm-dd)
and the Boiler and Pressure Vessel Safety Unit must be notified in writing by fax or mail.
Please include the Licence No. and the Serial Number on all correspondence.

(306) 787-1443 Phone/1-866-530-8559 (Phone - Toll free in SK)
(306) 787-9273 Fax/1-866-760-9255 (Fax - Toll free in SK)

☐ This report was discussed with the owner or his representative.

☐ A copy of this report was mailed to the owner/representative by regular mail on: (yyyy-mm-dd)

Holuk, Larry
952 - 122 3rd Avenue North
SASKATOON Saskatchewan S7K 2H6
(306) 933 - 5073 (Work)
(306) 220 - 3195 (Cell)
Larry.Holuk@sask.ca (Email)

Signature of Person receiving report: 2016-11-02 Inspection Data (yyyy-mm-dd)

Signature of Inspector: 0445 Inspector Number

CLIENT