



**Saskatchewan
Municipal Affairs,
Culture and Housing**

Boiler and Pressure
Vessel Safety Unit

1410 - 1855 Victoria Avenue
Regina, Saskatchewan
S4P 3V7

Certificate of Inspection

Issued under the provisions of The Boiler and
Pressure Vessel Act

Certificate No. 67535

Invoice:

To: Husky Oil Operations Ltd - Lloydminster
Highway 16 East
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Date Inspected: 07-06-00

Inspector: Amanie, James

Description:

Gas / Oil Separator

Ident. No. 7002969

Serial No. 2532

Length (meters): 1.52

W.P. Shell (Kpa): 4,965.00

W.P. Tube (Kpa):

Cash Numbers:

Unit No. 27374

K.W.

Diameter (meters): 0.58

Plant Capacity: 0.00

Inspection No. 925699

Location:

Husky Oil Operations
6-34-50-27 Lloydminster

Date Issued: 07-28-00

This certificate is valid only until the next inspection is performed.

Fee Paid: \$0.00 + \$0.00 (GST) = \$0.00

Certified Correct

Chief Inspector

**In the event of an explosion, rupture or serious overheating of a boiler or pressure vessel,
notice shall be sent forthwith to the Chief Inspector.**



Saskatchewan
Municipal Affairs,
Culture and Housing

1855 Victoria Avenue
Regina, Canada
S4P 3V7

Boiler and Pressure
Vessel Safety Unit

Inspection Report

No. 083744

925699

Ident. No.

7002969

Present
State

E

Type	Description	Location		Location Description	
4	Gas / Oil Separator	Husky Oil Operations 6-34-50-27 Lloydminster			

Jur.	Serial No.	CRN	Unit	Manufacturer	Mfg. Date	Dist.	Insp. No.	Mobility	Status
P	2532	K2422.2 (3)	27374	R J V Gasfield	1/94	10	2268 1138	P	A

Boiler Plant k/w	Boiler k/w	Tonnes Refrig. Pl.	Working Press/Tube	Working Press/Shell	Diameter	Length	Previous Condition Codes	Boiler Service	Boiler Press.	Insp. Method	Next Insp.
	0			4965	0.58	1.52				E	6/00 6/05

Send Bill to:

Husky Oil Operations Ltd - Lloydminster
Highway 16 East
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Send Certificate to:

Husky Oil Operations Ltd - Lloydminster
Highway 16 East
Lloydminster (Sask), Saskatchewan
S9V 0Z8

The following items of the above unit were inspected and tested where possible.

1.	Safety Valves	A	9.	Tubesheet		17.	Heads	
2.	Low Water Fuel Cut-off		10.	Tubes/Stays		18.	Staffing	
3.	Flow Switch		11.	Baffles/Refractory		19.	Boiler/Mach. Room Cond.	
4.	Limit Controls		12.	Inspection Openings		20.	Check Valve	
5.	Water Level Gauge	A	13.	Breeching & Smoke Pipes		21.	Data Report	
6.	Pressure/Temp. Gauges		14.	Water Legs		22.	Sask. Design Reg.	A
7.	Flame Scanner		15.	Associated Piping	A	23.	Name Plate	A
8.	Expansion Tank		16.	Shell	A	24.	Other	

Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/ Not Operating

Comments/Repairs or Corrective Action Required:

Items classified with an "R" must be repaired or corrected
before _____ and the Inspector notified.

- ☐ This report was discussed with the owner or his representative.
- ☐ A copy of this report was mailed to the owner or his representative on _____ by regular/registered mail.

JAMES AMANIE
Boiler & P.V. Inspector
Sturdy Stone Centre Bldg.
122 - 3rd Avenue N.
SASKATOON, Saskatchewan
S7K 2H6 PH: 933-6988

Signature of person receiving report

Inspection Date

Signature of Inspector

CLIENT