



**Saskatchewan
Corrections and
Public Safety**

3rd Flr - 1855 Victoria Avenue
Regina, Saskatchewan
S4P 3T2

Boiler and Pressure
Vessel Safety Unit

Certificate of Inspection

Issued under the provisions of The Boiler and
Pressure Vessel Act

Certificate No. 124764

Invoice:

To: Husky Oil Operations Ltd - Lloydminster
4429-44 Street
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Date Inspected: 04-01-05

Inspector: Amanie, James

Description:
Gas / Oil Separator

Ident. No. 7002969
Serial No. 2532
Length (meters): 1.52
W.P. Shell (Kpa): 4,965.00
W.P. Tube (Kpa):
Cash Numbers:

Unit No. 27374
K.W.
Diameter (meters): 0.61
Plant Capacity: 0.00
Inspection No. 969119

Location:
Husky Oil Ltd
6-34-50-27-W3

**Valid when repairs/corrective action per Inspection Report
number 969119 have been completed and until next inspection
is performed.**

Date Issued: 05-04-05

Fee Paid: \$0.00 + \$0.00 (GST) = \$0.00

C. M. Brown
Certified Correct

Brian Krasin
Chief Inspector

**In the event of an explosion, rupture or serious overheating of a boiler or pressure vessel,
notice shall be sent forthwith to the Chief Inspector.**

62019555

Corrections and
Public Safety1855 Victoria Avenue
Regina, Canada
S4P 3V7

Inspection Report

Boiler and Pressure
Vessel Safety Unit

No. 147565

Ident. No.	Present State
7002969	E

Community: Lloydminster (Sask)

969119

Type	Description	Location	Location Description
4	Gas / Oil Separator	Husky Oil Ltd 6-34-50-27-W3	

Jur.	Serial No.	CRN	Unit	Manufacturer	Mfg. Date	Dist.	Insp. No.	Mobility	Status
P	2532	K2422.2 (3)	27374	R J V Gasfield	1/94	10	2208	P	A

Boiler Plant k/w	Boiler k/w	Tonnes Refrig. Pl.	Working Press/Tube	Working Press/Shell	Diameter	Length	Previous Condition Codes	Boiler Service	Boiler Press.	Insp. Method	Next Inspect
	0			4965	0.58 0.61	1.52				E	5/05 4/10

Send Bill to:

Husky Oil Operations Ltd - Lloyd
4429-44 Street
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Send Certificate to:

Husky Oil Operations Ltd - Llo
4429-44 Street
Lloydminster (Sask), Saskatche
S9V 0Z8

The following items of the above unit were inspected and tested where possible.

1.	Safety Valves	A	9.	Tubesheet	/	17.	Heads	/
2.	Low Water Fuel Cut-off	/	10.	Tubes/Stays	/	18.	Staffing	/
3.	Flow Switch	/	11.	Baffles/Refractory	/	19.	Boiler/Mach. Room Cond.	/
4.	Limit Controls	/	12.	Inspection Openings	/	20.	Check Valve	/
5.	Water Level Gauge	/	13.	Breeching & Smoke Pipes	/	21.	Data Report	/
6.	Pressure/Temp. Gauges	A	14.	Water Legs	/	22.	Sask. Design Reg.	A
7.	Flame Scanner	/	15.	Associated Piping	A	23.	Name Plate	A
8.	Expansion Tank	/	16.	Shell	A	24.	Other	/

Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/ Not Operating

Comments/Repairs or Corrective Action Required:

Items classified with an "R" must be repaired or corrected
before _____ and the Inspector notified.

- ☐ This report was discussed with the owner or his representative.
- ☐ A copy of this report was mailed to the owner or his representative on _____ by regular/registered mail.

JAMES AMANIE
Boiler & P.V. Inspector
Sturdy Stone Centre Bldg.
122 - 3rd Avenue N.
SASKATOON, Saskatchewan
S7K 2H6 PH: 933-6988

Signature of person receiving report

April 2005
Inspection Date

Signature of Inspector

CLIENT