



**Saskatchewan
Corrections and
Public Safety**

Boiler and Pressure
Vessel Safety Unit

3rd Flr - 1855 Victoria Avenue
Regina, Saskatchewan
S4P 3T2

Certificate of Inspection

Issued under the provisions of The Boiler and
Pressure Vessel Act

Certificate No. 124763

Invoice:

To: Husky Oil Operations Ltd - Lloydminster
4429-44 Street
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Date Inspected: 04-01-05

Inspector: Amanie, James

Description:

Gas / Oil Separator

Ident. No. 7002968

Serial No. 2559

Length (meters): 1.52

W.P. Shell (Kpa): 4,965.00

W.P. Tube (Kpa):

Cash Numbers:

Unit No. 27373

K.W.

Diameter (meters): 0.61

Plant Capacity: 0.00

Inspection No. 969118

Location:

Husky Oil Ltd
6-34-50-27-W3

Valid when repairs/corrective action per Inspection Report
number 969118 have been completed and until next inspection
is performed.

Date Issued: 05-04-05

Fee Paid: \$0.00 + \$0.00

(GST) = \$0.00

C. M. Brown

Certified Correct

Brian Krasin

Chief Inspector

**In the event of an explosion, rupture or serious overheating of a boiler or pressure vessel,
notice shall be sent forthwith to the Chief Inspector.**

62037651

Corrections and
Public Safety1855 Victoria Avenue
Regina, Canada
S4P 3V7

Inspection Report

Boiler and Pressure
Vessel Safety Unit

No. 147564XXXXXX

Ident. No.	Present State
7002968	E

Community: Lloydminster (Sask)

969118

Type	Description	Location	Location Description
4	Gas / Oil Separator	Husky Oil Ltd 6-34-50-27-W3	

Jur.	Serial No.	CRN	Unit	Manufacturer	Mfg. Date	Dist.	Insp. No.	Mobility	Status
P	2559	K2422.2 (3)	27373	R J V Gasfield	1/94	10	2208	S	A

Boiler Plant k/w	Boiler k/w	Tonnes Refrig. Pl.	Working Press/Tube	Working Press/Shell	Diameter	Length	Previous Condition Codes	Boiler Service	Boiler Press.	Insp. Method	Next Inspect
	0			4965	0.58 0.61	1.52				E	6/05 4/10

Send Bill to:

Husky Oil Operations Ltd - Lloyd
4429-44 Street
Lloydminster (Sask), Saskatchewan
S9V 0Z8

Send Certificate to:

Husky Oil Operations Ltd - Llo
4429-44 Street
Lloydminster (Sask), Saskatche
S9V 0Z8

The following items of the above unit were inspected and tested where possible.

1.	Safety Valves	A	9.	Tubesheet		17.	Heads	
2.	Low Water Fuel Cut-off	/	10.	Tubes/Stays		18.	Staffing	
3.	Flow Switch	/	11.	Baffles/Refractory		19.	Boiler/Mach. Room Cond.	
4.	Limit Controls	/	12.	Inspection Openings		20.	Check Valve	
5.	Water Level Gauge	/	13.	Breeching & Smoke Pipes		21.	Data Report	
6.	Pressure/Temp. Gauges	A	14.	Water Legs		22.	Sask. Design Reg.	A
7.	Flame Scanner	/	15.	Associated Piping	A	23.	Name Plate	A
8.	Expansion Tank	/	16.	Shell	A	24.	Other	/

Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/ Not Operating

Comments/Repairs or Corrective Action Required:

Items classified with an "R" must be repaired or corrected
before _____ and the Inspector notified.

- ☐ This report was discussed with the owner or his representative.
- ☐ A copy of this report was mailed to the owner or his representative on _____ by regular/registered mail.

JAMES AMANIE
Boiler & P.V. Inspector
Sturdy Stone Centre Bldg. F.V. Inspector
122 - 3rd Avenue N. Sturdy Stone Centre Bldg.
SASKATOON, Saskatchewan SASKATOON, Saskatchewan
S7K 2H6 P5S 7K 2H6 PH: 363-5553

Signature of person receiving report

April 2005
Inspection Date

Signature of Inspector