



Saskatchewan
Municipal Affairs,
Culture and Housing

1855 Victoria Avenue
Regina, Canada
S4P 3V7

Inspection Report

Boiler and Pressure
Vessel Safety Unit

No. **083743**

925698

Ident. No.	Present State
7002968	E

Type	Description	Location		Location Description							
4	Gas / Oil Separator	Husky Oil Operations 6-34-50-27 Lloydminster									
Jur.	Serial No.	CRN	Unit	Manufacturer	Mfg. Date	Dist.	Insp. No.	Mobility	Status		
P	2559	K2422.2(3)	27373	R J V Gasfield	1/94	10	1138 2208	S	A		
Boiler Plant k/w	Boiler k/w	Tonnes Refrig. Pl.	Working Press/Tube	Working Press/Shell	Diameter	Length	Previous Condition Codes	Boiler Service	Boiler Press.	Insp. Method	Next Inspect
	0			4965	0.58	1.52				E	5/00 6/05

Send Bill to:	Send Certificate to:
Husky Oil Operations Ltd - Lloydminster Highway 16 East Lloydminster (Sask), Saskatchewan S9V 0Z8	Husky Oil Operations Ltd - Lloydminster Highway 16 East Lloydminster (Sask), Saskatchewan S9V 0Z8

The following items of the above unit were inspected and tested where possible.

1. Safety Valves	A	9. Tubesheet		17. Heads	
2. Low Water Fuel Cut-off		10. Tubes/Stays		18. Staffing	
3. Flow Switch		11. Baffles/Refractory		19. Boiler/Mach. Room Cond.	
4. Limit Controls		12. Inspection Openings		20. Check Valve	
5. Water Level Gauge	A	13. Breeching & Smoke Pipes		21. Data Report	
6. Pressure/Temp. Gauges		14. Water Legs		22. Sask. Design Reg.	A
7. Flame Scanner		15. Associated Piping		23. Name Plate	A
8. Expansion Tank		16. Shell	A	24. Other	/

Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/ Not Operating

Comments/Repairs or Corrective Action Required: _____

Items classified with an "R" must be repaired or corrected before _____ and the Inspector notified.

- This report was discussed with the owner or his representative.
- A copy of this report was mailed to the owner or his representative on _____ by regular/registered mail.

JAMES AMANIE
 Boiler & P.V. Inspector
 Sturdy Stone Centre Bldg.
 122 - 3rd Avenue N.
 SASKATOON, Saskatchewan
 S7K 2H6 PH: 933-6988

Signature of person receiving report _____ Inspection Date July 6/00 Signature of Inspector _____