

IRISNDT-CA-E-2051D



ULTRASONIC INSPECTION REPORT

CA1356-UT1-45

Page 2 of 3

Treater UT Vermilion Battery, AB 14-18-50-6W4

UT Location	Low UT Reading	Comments
UT-WH-1	0.565" 14.35	
UT-WH-2	0.581" 14.76	
UT-WH-3	0.576" 14.63	
UT-WH-4	0.571" 14.50	
UT-SHC6-1	0.518" 13.16	
UT-SHC6-2	0.524" 13.31	
UT-SHC5-1	0.530" 13.46	
UT-SHC5-2	0.531" 13.49	
UT-SHC4-1	0.529" 13.44	
UT-SHC4-2	0.526" 13.36	
UT-SHC3-1	0.541" 13.74	
UT-SHC3-2	0.533" 13.54	
UT-SHC2-1	0.535" 13.59	
UT-SHC2-2	0.530" 13.46	
UT-SHC1-1	0.527" 13.39	
UT-SHC1-2	0.532" 13.51	
UT-E-1	0.310" 7.87	
UT-E-2	0.311" 7.90	
UT-E-3	0.458" 11.63	
UT-E-4	0.310" 7.87	
UT-N-1	0.307" 7.80	
UT-N-2	0.314" 7.98	
UT-N-3	0.305" 7.75	
UT-N-4	0.309" 7.85	
UT-N-5	0.302" 7.67	
UT-N-6	0.324" 8.23	
UT-N-7	0.299" 7.59	
UT-N-8	0.301" 7.64	
UT-EH-1	0.604" 15.34	
UT-EH-2	0.725" 18.41	
UT-EH-3	0.676" 17.17	
UT-EH-4	0.614" 15.60	

IRISNDT #: LYN1901221

Date: 2019-Jul-25

Brady Harvey

(Print)


Client: HUSKY OIL OPERATIONS

(Sign)

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873
Calgary (403) 279-6121
Lloydminster (780) 875-6455
Barrhead (780) 674-3018
Nisku (780) 955-7616

Cold Lake (780) 826-6105
Fort McMurray (780) 743-1536
Red Deer (403) 347-1742
www.irisndt.com

Engineering, Calgary (403) 217-9684
Engineering, Edmonton (780) 437-2022
Rope Access Services (780) 437-2022
Offices also located in USA and UK





DAILY LEM TIME-TICKET

IRISNDT DAILY TICKET#

CA1356-DT-103

Page 1 of 1

Customer: HUSKY OIL OPERATIONS

IRISNDT DISPATCH #: LYN1901221

Location: Vermilion Battery, AB

Date: 2019-Jul-25

Technician 1: Brady Harvey Position: Junior Tech Technician 2: _____ Position: _____ Primary Activity: UT - ThicknessTechnician 3: _____ Position: _____ Technician 4: _____ Position: _____ Report Prefix: CA1356

Time Start	Time Finish	Activity	Report #s	LOC	Total Hours	Total KMs	Description	PO/Cost Code/AFE		Job #/Work Order #/Other	
07:00	08:30	Job Prep/Drive to Location	N/A	4	1.5	65	Job Prep/Drive to location	P.O.#:	TBD	W.O.#:	TBD
08:30	12:00	UT - Thickness	UT1-45	4	3.5		UT CML Locations	P.O.#:	TBD	W.O.#:	TBD
12:00	15:30	Drive Back To Shop/Reporting	UT1-45	4	3.5	65	Drive back to shop/Reporting	P.O.#:	TBD	W.O.#:	TBD
(Totals for this page only)					Totals:	8.5	130	Unit:			

Po 8401382216
wo# 8140614

Cory Bawtz 22-2012591



Work Location (LOC) Legend: 1) Inside Fab. Shop 2) Yard/Lay-down Area 3) Piping/Modular Fab. Area 4) Other

J.H.A. Carried Out & Documented: ☒ Yes ☐ No Safety Concerns: ☐ Yes ☒ No Safety Meeting: ☒ Yes ☐ No Living Out Allowance: ☒ N/A ☐ Full ☐ Bkfst ☐ Lunch ☐ Supper ☐ OT Meal ☐ Hotel

Equipment, Supplies, Consumables, and Other Costs

MIN

Additional Site, Daily, and other relevant job notes

REQ: Bob Marchak
Approver: TBDTECHNICIAN NAME: Brady Harvey
(Print)TECHNICIAN SIGNATURE: 
(Sign)CLIENT NAME: Karen Hawryluk
(Print)CLIENT SIGNATURE: 
(Sign)

Client Date: