



NONDESTRUCTIVE INSPECTION REPORT

VT-171653-02
Page 1 of 2

Type of Inspection: <u>UT / Visual</u>	Job/P.O.#: <u>see below</u>	IRISNDT #: <u>171653</u>	Date: <u>11-Dec-13</u>
Test Technique: <u>0 deg thickness</u>	Client: <u>Husky Energy Operations</u>		
Equipment: <u>DMS II, FH2E PROBE, FLASH LIGHT, GRINDER</u>	Location: <u>11-13-51-26W3, SK</u>		
	Item Inspected: <u>1000 bbITANK</u>		
	Code: <u>API 653</u>		

APPR: Brian Little
 APPR #: 2z-0527838
 PO# 8400706742
 REQ: Richard salzi
 WO# 25007113

A visual examination was carried out on 1000bbl tanks from the following location:

S/N: Tank 1 -5351-23

See the following page for results:

Unit#: <u>329</u> Kilometers: <u>50</u>	Consumables: MIN	Interpretation by: Danielle Lerche	SNT-TC-1A <u>1</u>
In: <u>1030</u> Out: <u>1230</u> Hrs: <u>2.0</u>		(Print) <u>Danielle Lerche</u>	C.G.S.B. <u>1</u>
In: _____ Out: _____ Hrs: _____		(Signature) Client Representative: (Print)	C.G.S.B. # <u>13551</u>
Personnel: Danielle LeRiche Amanda DeWolfe		I am in full agreement with report contents (Sign) <u>Ray Trachsel</u>	

5311 - 86 Street Edmonton, Alberta, T6E 5T8 Phone: (780) 437-2022 Fax: (780) 438-1436
 Calgary (403) 279-6121 Cold Lake (780) 826-6105 Deer Park, TX (281) 476-4444
 Lloydminster (780) 875-6455 Fort McMurray (780) 743-1536 Matrix, Houston, TX (713) 722-7177
 Barhead (780) 674-3018 Red Deer (403) 347-1742 Tulsa, OK (918) 446-8773
 Nisku (780) 955-7616