

Sho Rpt Rec'd

62062157

# IRISNDT

## NONDESTRUCTIVE INSPECTION REPORT

CA0342-NDT-760

Page 1 of 1

Type of Inspection: VT

Test Technique: VISUAL

Equipment: SPOTLIGHT

Code: CLIENT SPECS/ CLIENT INFO

Client: HUSKY OPERATIONS

IRISNDT #: LYD1601302

Location: 8-33-48-27 W3M,SK

Item Inspected: 1000 bbl tank s/n# 05.05.24.13885

Date: 29-Sep-16

WO #: 81130261

PO #: 8401084588

**TANK S/N# 05.05.24.13885:** travelled to site to evaluate tube after burner assembly was removed, the Firetube is bowed and will need to be replaced.

REQ: RYAN THOMPSON / RICHARD SALZL

APPROVER: RICHARD SALZL 2Z- 800473

Unit#: 767      Kilometers: n/c  
In: \_\_\_\_\_ Out: \_\_\_\_\_ Hrs: N/C  
In: \_\_\_\_\_ Out: \_\_\_\_\_ Hrs: \_\_\_\_\_

Personnel:  
STEPHEN BRYAN / MARSHALL LUNDELL

Consumables:

Interpretation by:

STEPHEN BRYAN  
(Print)

SNT-TC-1A: \_\_\_\_\_

C.G.S.B.: \_\_\_\_\_

(Level)

C.G.S.B. #: 12459

(Signature)

Client Representative:

(Print)

I am in full  
agreement with  
report contents

(Sign)

5311 - 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 fax: (780) 436-4873  
Calgary (403) 279-6121  
Lloydminster (780) 875-6455  
Barrhead (780) 674-3018  
Nisku (780) 955-7616

Cold Lake (780) 826-6105  
Fort McMurray (780) 743-1536  
Red Deer (403) 347-1742

www.irisndt.com

Engineering, Calgary (403) 217-9684  
Engineering, Edmonton (780) 437-2022  
Rope Access Services (780) 437-2022  
Offices also located in USA and UK

IRISNDT-E-2015E