

	<b>MAGNETIC PARTICLE INSPECTION REPORT</b>	<b>CA1356-MT3-55</b> Page 1 of 2
--	--	-------------------------------------

<b>Procedure:</b> 5.0 <b>Technique:</b> MT-2V <b>Code/Standard:</b> API 650 - Sect 8.2.4 <b>Other:</b> Crack Detection	<b>Rev:</b> 3 <b>Client:</b> HUSKY OIL OPERATIONS <b>IRISNDT #:</b> LYN1901481 <b>Location:</b> 4-22-45-6W4 <b>Item Inspected:</b> Lifting Lugs	<b>Date:</b> 2019-Sep-05 <b>WO #:</b> 81416940 <b>PO #:</b> 8401382216
---	---	--

<b>Project Name:</b>	<b>Project #:</b>
<b>Specification:</b>	<b>Standard:</b>

<b>Surface Condition:</b> As Welded	<b>Material:</b> Carbon Steel	<b>Thickness:</b> 3/16"	<b>Heat Treatment:</b> Not Applicable
<b>Magnetizing Equipment:</b> Yoke	<b>Method of Magnetization:</b> AC Continuous	<b>Asset #:</b> 40099	<b>Mfg:</b> Contour Probe
<b>Verification Date:</b> 2019-Sep-05	<b>Verification Weight:</b> <input checked="" type="checkbox"/> 10 lb. <input type="checkbox"/> 40 lb.	<b>Asset #:</b> 49283	<b>Verification per ASME V Art 7 T-762</b>

<b>Magnetic Particles:</b> Dry <input type="checkbox"/> Wet <input checked="" type="checkbox"/>	Red <input type="checkbox"/> Grey <input type="checkbox"/> Black <input checked="" type="checkbox"/> Fluorescent <input type="checkbox"/>	
Batch #: G5050318	Manufacture: Ardrex	Type: 8032 Aerosol

<input checked="" type="checkbox"/> <b>Background</b>		
Batch #: G5110817	Manufacture: Ardrex	Type: 8901W

<input type="checkbox"/> <b>Blacklight (N/A)</b>		
Asset #:	Blacklight meter: Asset #:	Cal Due Date:

<input checked="" type="checkbox"/> <b>Whitelight</b>	
Lighting Equipment: Flashlight Standard Bulb (4xAA)	Verification per ASME V Art 7 T-777.1

<b>Inspection Scope:</b> To perform a wet black on white magnetic particle inspection on the following (3) Lifting Lugs
---


**Requisitioner:** Kristy Leeson    **Approver:** Glen King    22-02003834    S/N: D-03-125S1



- Typical Lifting Lug


**Results:** At time of inspection all welds were acceptable to code.

<b>Inspection Limitation(s):</b>
----------------------------------

Unit#: 667    Kilometers: _____ In: _____ Out: _____ Hrs: _____ In: _____ Out: _____ Hrs: _____ Personnel: Brady Harvey,	Consumables: min	Interpretation by: <div style="text-align: center;"> <b>Brady Harvey</b>          (Print)           (Sign) _____       </div> Client Representative: _____ (Print) _____ I am in full agreement with report contents (Sign) _____
		SNT-TC-1A: 2 C.G.S.B.: 2 (Level) C.G.S.B #: 20503

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake (780) 826-6105 Lloydminster (780) 875-6455 Fort McMurray (780) 743-1536 Barrhead (780) 674-3018 Red Deer (403) 347-1742 Nisku (780) 955-7616 www.irisndt.com	Engineering, Calgary (403) 217-9684 Engineering, Edmonton (780) 437-2022 Rope Access Services (780) 437-2022 Offices also located in USA and UK
--	--





IRISNDT #: LYN1901481

Date: 2019-Sep-05

Brady Harvey

(Print)

*Brady Harvey*

(Sign)

Client: HUSKY OIL OPERATIONS

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873  
 Calgary (403) 279-6121  
 Lloydminster (780) 875-6455  
 Barrhead (780) 674-3018  
 Nisku (780) 955-7616

Cold Lake (780) 826-6105  
 Fort McMurray (780) 743-1536  
 Red Deer (403) 347-1742  
[www.irisndt.com](http://www.irisndt.com)

Engineering, Calgary (403) 217-9684  
 Engineering, Edmonton (780) 437-2022  
 Rope Access Services (780) 437-2022  
 Offices also located in USA and UK

