



PRV INSPECTION AND TEST REPORT

BRANCH: Grande Prairie

UVL ID#: 6442G

Work Order: W15001146

Customer PO#:

Customer: CENOVUS ENERGY INC

Date: 04/29/2019

Facility: ELMWORTH FIELD

LSD: 02-27-070-13W6M

PSV Location: FUEL GAS

A#: N/A

Vessel SN:

Cust Id: G709851

Cust. Ref.: N/A

Valve PO:

PO LINE#:

Cust. WO#:

Cust AFE#:

Cost Centre#:

VALVE DATA

Man.: MERCER Model: 91-12D511807E Serial: 5516 Seat: SOFT
Conn. Threaded Inlet: 0.75" MNPT Orifice: D Outlet: 1" FNPT Vacuum:
Set Press. 125 PSI Back Press.: 0 PSI CDT: 0 PSI Temp: 70 F Cap: 279 SCFM
Lift Lever ☐ Cap Assembly: Closed RFID: Code Symbol: UV CRN#: OG2606.5C

CUSTOMER INSTRUCTIONS

Instructions: Full Service

Pretest Required? ☒Reset Required? ☐

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: 06/2013
Seal Condition: Top: Intact Bottom: N/A Insignia: UVL Fittings Attached: Inlet: ☐ Outlet: ☐
Inlet: Carbon Inlet Plugged: ☐ Outlet: Carbon Outlet Plugged: ☐ Initial Insp. Signoff: Ray Tolentino

PRETEST 1

Simmer: 147 PSI Set Press: 149 PSI Reseat: 90 PSI Leakage: 3+ BPM Test Gauge: GP10K-1/2
Tested By: Don (Rodrigo) Menese Pretest Comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test Gauge: GP10K-1/2
Tested By: Pretest Comments:

COMPONENTS INSPECTION

(0 Like New / 1 Minor / 2 Medium / 3 Major)

ITEM	CLEAN	OILY	RUSTY	CARBON	PITTED	CORRODED	SCALE	VIBRATION	GROOVED	DENTED	GALLING	GOUNDED	OTHER	Machined	Lapped	Polished	Replaced	Replace Next Service	COMMENTS
DISC									1					☐	☐	☐	☒	☐	
NOZZLE										1				☐	☐	☐	☒	☐	
CAP-LEVER ASSY	1													☐	☐	☐	☐	☐	
COMP SCREW and LC		1												☐	☐	☐	☐	☐	
AS FOUND: SPRING and BUTTON:		1												☐	☐	☐	☐	☐	
SPINDLE / STEM														☐	☐	☐	☐	☐	
STEM RETAINER														☐	☐	☐	☐	☐	
DISC HOLDER		1												☐	☐	☐	☐	☐	
GUIDE / UPPER RING														☐	☐	☐	☐	☐	
LOWER RING														☐	☐	☐	☐	☐	
RING PIN(S)														☐	☐	☐	☐	☐	
BELLOWS														☐	☐	☐	☐	☐	
GASKET / SEALS													1	☐	☐	☐	☒	☐	WORN
CONNECTION ENDS		1												☐	☐	☐	☐	☐	
OTHER														☐	☐	☐	☐	☐	

DISC: Min: SUB ACT - NOZZLE: MIN / MAX SOFT ACT - SPRING NUMBER: NO #
Disassembly: Jasper Piezas Inspection: Tyler Dahl Reassembly: Jasper Piezas

FINAL TEST

Test Medium Air Simmer: 123 PSI Set Pressure 125 PSI
Reseat: 94 PSI Leakage Acceptable: ☒ B.P. Test: 60 PSI Vacuum:
ADJ. RING SETTING (NOTCHES): Upper: Lower: Test Gauge: GP5K-1/2 Set Press Def POP
Tested by: Don (Rodrigo) Meneses Jr. Date Final Tested: 04/30/2019

FINAL INSPECTION:

SEAL: Top: ☒ Bottom: ☐ End Protectors Installed: ☒ Painted: ☒ Palletized: ☐ Ship Container: ☒ Flex Gaskets Supplied: ☐
Final Inspection: Ray Tolentino Customer Inspection:
Comments: - SERVICE RATING: ROUTINE

PASS

Reviewed By

MAY 30 2019

LYNETTE DUMAS

REVISION 0 MAY-01-2018 QF-056A