INSPECTION REPORT

HUSKY OIL (LLOYDMINSTER)

TANGLEFLAGS Insp. Date: 11/09/2001

Name:

CONTACTOR

Location:

TANGLEFLAGS BATTERY

Date:

Equip. #:

S04-01-00V-SN94210AA

LSD

A3-31-50-25W3

Prov. #:

S/N 94210AA

Serial #:

94210-AA

Insp. Type:

ON STREAM

Tag #:

S/N 94210-AA

VI: No

UG: Yes PT: No

HT: No

US: No

VE: Yes

LT: No

RT: No

MT: No

OTHER: No

Observations

Inspector: Ray Trachuk

11/09/2001

01/24/2002

Summary

- Contactor was found to be in fair condition and suitable for continued service.

Details

- Visual inspection of the contactors external surfaces did not reveal any concerns at time of inspection.

- UT thicknesses tests were performed on the shell and bottom head of the contactor with all areas tested exceeding the nominal thicknesses shown on the nameplate. See attached sketch for thicknesses found and approximate locations of tests.

- The contactor is protected by PSV # 1328 and was last serviced on 97-10-15.

Recommendations

Inspector:

Summary

- The PSV protecting the contactor should be serviced prior to recommissioning the vessel.

Details

- Inspect the contactor in two years.

cc: Howie Staniforth Dennis McKague

Reviewed By:

2. Dagoz 20202

Date:

01/24/2002

